

AMiRo-OS - Bug #595

SSSP has issue with IO event in breakout board

2019-04-01 17:25 - Cung Lian Sang

Status:	New	Start date:	2019-04-01
Priority:	Normal	Due date:	
Assignee:	Cung Lian Sang	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description Enabling the SSSP flag has some conflicts with the IO event in the UWB breakout board of the Light Ring module. The UWB breakout uses a PB9 pin as an event trigger. The application of UWB is working as expected when the SSSP flag (AMIROOS_CFG_SSSP_ENABLE) is disabled. However, when the SSSP flag is enabled, the event is not triggered any more on the breakout board.			

History

#1 - 2019-08-08 09:24 - Cung Lian Sang

- % Done changed from 0 to 100