

## AMiRo-OS - Issues

| #   | Tracker | Status   | Priority | Subject  | Assignee         | Updated          |
|-----|---------|----------|----------|--|------------------|------------------|
| 596 | Feature | New      | Normal   | automated test script                          |                  | 2019-11-14 11:52 |
| 595 | Bug     | New      | Normal   | SSSP has issue with IO event in breakout board | Cung Lian Sang   | 2019-08-08 09:24 |
| 594 | Feature | Resolved | Normal   | Revise periphAL                                | Thomas Schöpping | 2019-11-14 09:57 |
| 591 | Feature | New      | Normal   | More generic QtCreator project setup           |                  | 2019-03-08 13:20 |
| 589 | Feature | New      | Normal   | Enhanced I/O events                            |                  | 2019-03-08 13:13 |
| 587 | Feature | New      | Normal   | Implement I2C bus clear function               | Felix Wittenfeld | 2019-02-25 17:02 |