

AMiRo-OS - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|-----|---------|-------------|----------|--|------------------|------------------|
| 595 | Bug | New | Normal | SSSP has issue with IO event in breakout board | Cung Lian Sang | 2019-08-08 09:24 |
| 586 | Feature | New | Low | Configurable shell history | Thomas Schöpping | 2019-02-25 16:53 |
| 587 | Feature | New | Normal | Implement I2C bus clear function | Felix Wittenfeld | 2019-02-25 17:02 |
| 589 | Feature | New | Normal | Enhanced I/O events | | 2019-03-08 13:13 |
| 591 | Feature | New | Normal | More generic QtCreator project setup | | 2019-03-08 13:20 |
| 596 | Feature | New | Normal | automated test script | | 2019-11-14 11:52 |
| 588 | Support | In Progress | High | AMiRo-BLT overhaul | Marc Rothmann | 2019-03-08 11:57 |