

## AMiRo-OS - Issues

| #   | Tracker | Status      | Priority | Subject  | Assignee         | Updated          |
|-----|---------|-------------|----------|--|------------------|------------------|
| 588 | Support | In Progress | High     | AMiRo-BLT overhaul                             | Marc Rothmann    | 2019-03-08 11:57 |
| 596 | Feature | New         | Normal   | automated test script                          |                  | 2019-11-14 11:52 |
| 586 | Feature | New         | Low      | Configurable shell history                     | Thomas Schöpping | 2019-02-25 16:53 |
| 589 | Feature | New         | Normal   | Enhanced I/O events                            |                  | 2019-03-08 13:13 |
| 587 | Feature | New         | Normal   | Implement I2C bus clear function               | Felix Wittenfeld | 2019-02-25 17:02 |
| 591 | Feature | New         | Normal   | More generic QtCreator project setup           |                  | 2019-03-08 13:20 |
| 595 | Bug     | New         | Normal   | SSSP has issue with IO event in breakout board | Cung Lian Sang   | 2019-08-08 09:24 |