

AMiRo-OS - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
595	Bug	New	Normal	SSSP has issue with IO event in breakout board	Cung Lian Sang	2019-08-08 09:24
587	Feature	New	Normal	Implement I2C bus clear function	Felix Wittenfeld	2019-02-25 17:02
589	Feature	New	Normal	Enhanced I/O events		2019-03-08 13:13
591	Feature	New	Normal	More generic QtCreator project setup		2019-03-08 13:20
596	Feature	New	Normal	automated test script		2019-11-14 11:52
586	Feature	New	Low	Configurable shell history	Thomas Schöpping	2019-02-25 16:53
588	Support	In Progress	High	AMiRo-BLT overhaul	Marc Rothmann	2019-03-08 11:57